

Ohs Inc. /Ohio hydraulic Service
7733 Lydia Dr.
Lewis Center, Oh 43035-8075
Ph 614-221-8495 Fax 614-221-6246
business@ohiohydraulic.com

HEIN-WERNER MODEL 62 TRANSMISSION JACK.

The Model 62 has been replaced with the New Model HW93718.

It is basically the same jack with a newly designed hydraulic power unit. For customers who would like to repair their old jacks there are a couple of choices. You can replace the old Power unit with the new 261169A which is now a complete power unit and handle assy. This unit should fit most old jacks. The frames are basically the same so you should not have any issues replacing the normal fast wearing parts.

You can repair your old Power unit but parts are limited to a repair kit for the power unit and an upgrade pump kit shown below. You will have to use your old handle and drill out the two mounting holes from 5/16th to 3/8th to accept the new pins. You can also buy a new handle if your old handle cannot be used. The only part available other than this kit and handle is a soft seal aftermarket repair kit number 80758. All these items can be found in our web store at the following address. Just use the Search function to find and buy your parts.

<http://www.ohiohydraulic.com/store/index.html>

80758 REPAIR KIT

7605A PUMP KIT

261169 POWER UNIT /WITHOUT HANDLE

261169A POWER UNIT WITH HANDLE

245828 HANDLE WELDMENT ONLY. NO GRIP OR PINS



7605A